What We Can Learn from Sailing Accidents to Benefit Sailors

Sally Lindsay Honey, Chair, Safety at Sea Committee

Chuck Hawley, Past Chair, Safety at Sea Committee



Sailing Incidents

What happened in 6 incidents? How they have changed sailing.
Lessons Learned Incorporated into:
Equipment Requirements Training
Vessel Limitations Crew Expertise







3 Incidents, 7 souls

- Low Speed Chase, Sydney 38
 - Safe Water Depths
 - April 14, 2012: 5 crew lost
- Imedi, TP 52
 - Boat Control near COB
 - July 21, 2018: 1 crew lost
- Morpheus, Moore 24
 - COB Recovery Equipment
 - March 13, 2019: 1 crew lost
- ALL: Inadequate Flotation



Farallones Race San Francisco April 14, 2012

A normal lively sailing day -





turned tragic:
Breaking wave
Lee Shore
5 of 8 crew lost



Failure of seamanship in negotiating shoal waters on a lee shore





Lost At Sea -



Alan Cahill Alexis Busch Marc Kasanin Jordan Fromm Elmer Morrissey

No tethers: 5 of 7 in the water were lost; one on boat survived. Survivors wore life jackets that met US Sailing 5.0.1 Compromised buoyancy in surf/aerated water

US Sailing

12 days later: USCG Capt. Stowe called for Stand Down in Gulf of the Farallones



Restricts offshore races to line from Mt. Bonita to Land's End "San Francisco offshore sailboat racing organizations need to review racing safety protocols and seek improvement"



USCG asked US Sailing to Investigate:

1. **Failure of seamanship** in negotiating shoal waters on a lee shore was the only direct cause

2. **Inadequate personal safety gear** in use for offshore conditions, could have saved lives

3. Limited VHF communication infrastructure hampering race committee-to-race boat communications

4. Race management protocol flaws created uncertainty surrounding search and rescue efforts



Only Prevention: more conservative course



Recommendations from LSC Tragedy

- 1. Annual Training to improve seamanship, specifically on breaking wave development.
- 2. Require personal flotation to meet USS prescription 5.0.1, training in jackline rigging and use, spot inspections to ensure MER compliance.
- 3. Improve VHF communication infrastructure
- 4. Improve race management accountability of boats and crew on the race course.

Safe Water Depths:

Significant Wave Height/SWH = *average* of largest 1/3 of all waves. Forecast: wind waves 7' on 15' swell Maximum: 30 feet, 2-3 per hour = 25'





Calculate minimum depth from maximum forecast swell and wind-wave heights: 3 ways

Easiest: 2.5x the sum of maximum forecast swell and wind-wave heights

For April 14th forecast: 1) 43', 2) 55', and 3) 45-60'



Inadequate personal safety gear for offshore conditions

- Racers required to "have" lifejackets to meet US SAILING 5.0.1, but only wear "adequate" flotation
- Category 2 requirements not met by two crew
- Of crew in water, those wearing 5.0.1 life jackets survived, none had thigh straps
- Jacklines deployed per requirement, not used









Direct Results – NorCal ORC

Seamanship – Skippers' meetings: local conditions

More variety of Safety at Sea course formats:
 ¹/₂ day, full day, 2 day

 Safety gear – SERs created, consistent among all OAs, inspections required

Imedi, TP 52, Chicago- Mackinac Race, 21 July 2018, Jon Santarelli/COB lost





Wide open cockpit: no jack lines near vang control

Imedi recovery attempts



Jon Santarelli was fit, conscious, swimming. Why did he drown?





CO2 cartridge not pierced until recovered 1 week later

Life Jacket Maintenance & Understanding:

- Cursory pre-inspection of 10+ year old life jackets
- Crew not familiar with boat-supplied life jackets
- No attempt by PIW to manually/orally inflate life jacket



Other Issues:

2. Obligatory COB Practice:

inside breakwater, under power

- 3. Command Structure: poorly defined
- 4. Unused Equipment:LifeSling,MOM





Lessons Learned

- 1. Comprehensive Dock Talk: command structure, crew roles, procedures
- 2. Establish/communicate COB procedures
- 3. Safety gear: Inspect, fit, instruct prior to use
- 4. Practice in expected conditions
- 5. As PIW: act immediately
- 6. Enhanced training needed for inflatable lifejackets



Safe COB Recovery in seaway:

Alternative Possibilities:

- Swimmer of the watch (Professional crews)
- Lower crew on halyard (Adequately fit crew)
- Modified LifeSling 1:2
 retrieval



Flat bottom, fin keel







Safe COB Recovery in Seaway:

- 1. Push MOB button
- 2. Slow boat, Lower headsail
- 3. Sail by COB Ensure adequate flotation, don't stop
- 4. Dowse main, motor back
- 5. Drag LifeSling around COB
- 6. Stop boat, drift
- 7. Hook spinnaker halyard to tow line outside lifelines, do not disconnect.
- Hoist COB on 1:2 purchase up and over lifelines



Morpheus, Moore 24 Monterey Bay Wednesday Evening Race, March 13, 2019 – COB drowned



Windy conditions, but not unusual for Monterey Bay





Recovery Attempts, Morpheus crew:



Figure 8, twice. Lost grip: "Hurry" Threw line, upwind, Dale falls in



Recovery Attempt, Loca Motion, Express 37

GPS Track and Notes of Loca Motion 3/13/19



Lessons Learned

Stay attached to boat Consider use of lifelines Cause of death: drowning due to inadequate flotation Use of Lifesling could have provided flotation Crisis stress > additional people in water Cold water acts quickly



Inflatable Lifejackets

Still the best option Integrate harness, tether Must be understood, maintained, checked Must be adjusted to fit US Sailing to survey inflatable lifejacket failures New clinics specific to life jacket wear & care







It's not just sailboats or recreational boaters...

"human errors on a multitude of levels as the root cause of the accident"

COTUNA

"the watch officer onboard the Tunisian ro-ro Ulysse was alone on the bridge and was on his phone"



Vestas Wind Volvo Ocean Race November 29, 2014



Volvo Ocean Race 2014-2015

- 10 Leg, 39,000 mile race
- 8 crew plus a media professional
- 65' one-design boats
- Hazardous courses







25 degree angle of heel, lots of sails, small radar, constant sail trimming...

New Route for 2013-2014 Race







Image Landsat / Copernicus Data SIO, NOAA, U.S. Navy, NGA, GEBCO Image © 2020 Maxar Technologies

Google Earth


C-MAtherenant betandermine if Area



Big blue area showing depths less than 200m



Territorial sea boundaries



Chart "bounds"



Spot Soundings



A name of a physical feature with "shoal" in it



C-MAP Chart, zoomed in









Lessons Learned:

- Exclusion zone changed ~ 36h before race start
- Navigator and skipper did not zoom in on C-Map charts; were completely unaware of the danger
- Conditions they encountered matched what they had imagined and warned the crew about
- Did not use radar or depth sounder because there was no perceived need.
- C-Map charts were not effective at alerting the crew to the danger of the reef



The Loss of Clipper Ventures 24

Information and Images from MAIB Accident Report "Report on the investigation of the grounding and loss of the UK registered yacht CV24 at Cape Peninsula, South Africa, on 31 October, 2017



ACCIDENT REPORT



Report on the investigation of the

grounding and loss

of the UK registered yacht

CV24

at Cape Peninsula, South Africa,

on 31 October 2017



VERY SERIOUS MARINE CASUALTY

REPORT NO 12/2018



Clipper Round the World Race

- Pay-to-sail race around the world on 12 identical 70 foot sloops
- One professional captain on each yacht
- Extensive training program prior to the event
- Sailors can sign up for one or more legs or the entire race
- Course is similar to Volvo Ocean Race with about 12 legs; passes through Panama Canal





The Race Course



Previous Incidents

Groundings

Loss of CV4, Indonesia, 1/2010 Crew overboard, successful, 3/2014 Gybe causing trauma, fatal, 2015 Crew overboard fatal, 11/2017 Crew overboard, fatal, 12/2017

Mandatory reporting to Head of Training Successful MOB recovery Crash or accidental gybes 25 months: 107 reported incidents



Aground in Brazil during 2015-2016 Race



Derry~Londonderry~Doire MOB 3/31/2014



Timeline

23:43 UTC Man Overboard, initiated MOB procedure
00:55 UTC Crewmember sighted
01:13 UTC Crewmember recovered

90 minutes in the water. Crew made full recovery.







Path of CV24 from the start of Leg 3, along Cape Peninsula

Winds initially out of the NE; began to back as fleet went south.

Breeze freshened from the north, then NNW



Paths of vessels along Cape Peninsula



COG



SOG VMG













Lessons Learned

- 1. Loss of situational awareness was the proximate cause of the grounding, i.e. navigation was ignored so that the gybe could be safely carried out.
- 2. A lack of a passage plan made it more difficult to determine that the vessel was off-course
- 3. Navigational training was not part of their comprehensive training program.
- 4. Key navigational information was either not displayed or not available on deck.



2017-2018 Volvo Ocean Race Collision on Leg 4



Fleet was headed from Melbourne to Hong Kong

TWA of 150, 21kts of boat speed

Encountered a mass of coastal fishing boats

Collision between V11 and one of the boats on her port bow about 30 miles from the finish

The captain of the fishing boat was killed in the collision

Vestas 11th Hour Racing stayed on site and helped rescue the fishermen after the collision





Philippines to Port





Trends in Long Distance Offshore Racing

Boats are faster with fewer sailors

Routes cross the equator more frequently

Fleets sail in congested waters: Qingdao, Hong Kong, Gibraltar, Brazil, Strait of Malacca

Sponsorship drives the route choices



Fishing Vessel Activity by AIS, Sept 2017



Fishing activity near Qingdao (beige boats are fishing vessels)





Image courtesy of MarineTraffic

Heel + spray + jibs on the water = tough watchkeeping.



Risk Factors



- 1. Limited visibility from the sailboat
- 2. Limited visibility of the sailboat from surrounding vessels
- 3. Local fleets unaware of the vessels' arrival or speed
- 4. AIS in near universal use, but may be on nets or skiffs
- 5. Fishing vessels are lit, but not with IRPCAS lights


Dipping the Bow

Helmsmen would bear off 10-20 degrees periodically to allow them to see beyond/behind the luff of the headsail





Crew to Leeward

Watch captains position a grinder or an extra crewmember to leeward to wait for an opportunity to view what is under the sail





Timing is everything

Crews to leeward in the cockpit would have to wait for the sailboat to be on a crest to get the best view





Less overlap = more visibility

Crews indicated that the A3 and MHO, due to their overlap, presented the greatest visibility issues. Shorter LP sails, like the FRO, were easier to see around.





Navigation light conundrum

Up to 20m, vessels can use a combined nav light at the masthead for sailing

Above 20m, separate sidelights and a sternlight

Cannot be used under power, necessitating additional lights

Lights at the sheerline are blocked by sails

Lights on the prod are frequently underwater





VO 65 solution

Three LED modules, mounted to the carbon wind sensor mast

Not blocked by anything but the Windex and VHF antenna





Making the sailboats easier to see

Both deck-levels lights and masthead lights have advantages

- 1. Use both, especially in harbors or areas that are backlit by city lights
- 2. Add a blinking light to the tricolor light to bring attention to it
- Illuminate the head of the mainsail with uplights on the uppermost spreader, without blinding the crew or skipper



Current "tricolor" light



Current "tricolor" light with "uplight"



Prod-mounted and "tricolor" lights

Sheerline and "tricolor" lights

Blinking and "tricolor" lights

Actions Taken

Extensive investigation into causes of the collision.
VO65s fitted with much better radar for anti-collision.
Better AIS antenna installations.
World Sailing letter to IMO explaining the problem and requesting clarification of COLREGS.



IT IS TIME FOR THE

SOCIAL MEDIA MINUTE

Please take 60-seconds and post one takeaway, picture or thought from this session on a social media platform of your choice and tag @USSailing @(presenter)

@(presenter) #SailingLeadership



Your Opinion Matters

Please open the Sailing Leadership Forum app and complete the session survey found in the menu bar.

Thank you for attending this session

